

**ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE
REGULATORY CONTACT RECORD**

Date/Time September 6, 2001

Site Contact(s) Kent Dorr

Phone 966-6034

Regulatory Contact. Dave Kruchek

Phone 966-6728

Agency CDPH&E

Purpose of Contact Confirmation of Email from Dave Kruchek to Kent Dorr regarding Building 881 Work Packages

Discussion

Email from David Kruchek to Kent Dorr dated 9/6/01 (4 19PM) states the following

Kent, I have reviewed the work packages presented this week and last and concur with the following work packages

- 1 T0104716-301 - Disassemble and remove Annular Tank, Pumps, lines and Metal Table from Room 286 Taking appropriate measures with possible liquids that may be encountered
- 2 T0104716-306 - Isolate and remove electrical power to Building 830 and Building 890
- 3 T0104716-302 - Disassemble and remove Helium Farm Although these lines are indicated to have been isolated, appropriate precautions need to be taken with identifying and managing any possible contamination that may have entered the lines from Building 881
- 4 T0104716-312 - Disassemble and remove the East and West HVAC Units in Room 161 However unlikely, special consideration needs to be made for possible contamination inside the units and ducts that may have come from the lab Room 143
- 5 T0104716-307 Disconnect and isolate steam to Building 885

I also concur with the disconnection and removal of the glovebox and pipe rack in Room 282 (part of T0104716-304), which is open and has been properly surveyed for Be and Rad concerns This glovebox appears to be free of Be or Rad contamination Disposal of this glovebox must consider the possible lead in the windows and other possible lead or other metals that may make this a RCRA waste

However, I cannot concur with the proposed disconnection and removal of the glovebox and ancillary equipment located in Room 233 (part of T0104716-304) The appropriate

Contact Record 9/6/01
Rev 10/11/00

DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE

Page 1 of 2

ADMIN RECORD

B881-A-000010

1/2

safeguards do not appear to be in place for this glovebox, which is not open and may contain interior contamination Prior to allowing this activity to occur please provide additional detail regarding the actions to be performed and safeguards implemented to properly characterize and disassemble this glovebox and equipment

Contact Record Prepared By Kent A Dorr

Required Distribution

J Legare, RFFO	C Albin, RFCSS	S Nesta, K-H
S Tower, RFFO	D Bryant	K North, K-H
S Gunderson, CDPH&E	C Deck, K-H	H Padron, RFCSS
D Kruchek, CDPH&E	S Gianti, K-H	D Parsons, K-H
(rehder timothy@epamail.epa.gov)	F Gibbs, K-H	J Robbins, K-H
	S Knopp, K-H	T Scott, K-H
	K Myers, K-H	D Shelton, K-H

